

6929 N. Lakewood Avenue Tulsa, OK 74117

PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

August 30, 2024

Carrier: Verizon Maryland LLC, 1710 Underpass Way, Hagerstown, MD 21740

Contact: For additional information on these planned network changes, please contact:

Lisa M Thompson Global Engineering and System Performance Verizon Wireline Network Operations 13100 Columbia Pike Silver Spring, MD 20904 (410) 375-9777

Quadre Washington
Senior Manager – Global Engineering and System Performance
Verizon Wireline Network Operations
320 Saint Paul Place
Baltimore, MD 21202
(410) 736-4261

Implementation Date: On or after March 1, 2025

Planned Network Change(s) Will Occur at the Following Maryland Location(s):

Verizon Central Office	Address	CLLI
	7781 Landover Road	LDVRMDLODS0
	Landover, MD 20785	LDAKINIDLOD20
Hyattsville MD CS2K Switch	5500 Baltimore Avenue	HYVLMDHYPS0
_	Hyattsville, MD 20781	HIVLINIDHIP30

This notice may also be viewed at:

http://www.verizon.com/about/terms-conditions/network-disclosures

PLEASE NOTE:

- All references to the Landover MD 5ESS switch are associated with CLLI code LDVRMDLODS0 and will not be repeated throughout the notice.
- All references to the Hyattsville MD C2SK switch are associated with CLLI code HYVLMDHYPS0 and will not be repeated throughout the notice.

Description of the Planned Network Change(s):

The Verizon Landover MD 5ESS switch, located at 7781 Landover Road, Landover, MD 20785, will be retired and removed from the Verizon network after all traffic served by this switch is migrated to the Hyattsville MD C2SK switch, located at 5500 Baltimore Avenue, Hyattsville, MD 20781. All traffic to be migrated to the Hyattsville MD C2SK switch includes, but is not limited to, Inter-LATA (ACCESS/FG-B-D/CLEC IXC), wireless and paging traffic.

Description of Reasonably Foreseeable Impact(s) of the Planned Change(s): All carriers, including competitive local exchange carriers (CLECs), Interexchange carriers (IXCs, IECs), wireless carriers, and paging carriers, will need to provision new trunk groups to support direct end office trunking to the Hyattsville MD C2SK switch or have existing trunk groups to that switch augmented.

All ASRs for the Hyattsville MD C2SK must be received no later than **November 19**, **2024**, to provide sufficient time to migrate the traffic described above. Local Exchange Routing Guide (LERG) change effective dates will be posted prior to decommissioning of the Landover MD 5ESS switch (**on or after March 1, 2025**). This will serve to guide interconnect re-routes of traffic for the NPA codes currently served by the Landover MD 5ESS switch to reflect the Hyattsville MD C2SK switch as the new home switch. All trunks to the Hyattsville MD C2SK switch must be in place prior to the decommissioning of the Landover MD 5ESS switch. All ASRs for the Hyattsville MD C2SK switch must carry a project code of **LDVRMDLODS0**.